

Dorothy Brown Before Pictures

TDHCA Reservation: 100389103

101 Fenner St. Cuero, TX 77954

Administrator: Crossroads Community Action



Street View



Drive Way



Side Walk

Drawing of Portch, Sidewalk, and Ramp.



8 inch step from sidewalk to porch



6 inch step from porch to door jam

Step from Sidewalk and Step from Porch to door




Entryway Storm Door should swing opposite direction to allow for person using walker room to open door. Currently opens so that the pillar of the front porch is a pinch point.



Din has two 6” step drops with a bad handrail. Ideally, would like an electric platform lift here. Or at least two new sterdy handrails.



2 x 6" steps to Dining Room from Din



12" Drop from Dining Room to Din (family room)



Carport where client parks their car.



Rear entrance into client's Din that is two-steps lower than the rest of the house.



Dining Room

Kitchen



Kitchen from Dining Room



Laundry Room Entrance from Dining Room



12" Step Down into Laundry Room from Dining Rm



2x6" Step Up from Laundry Room to Dining Room



Top Load Washer and Broken Gas Dryer




Hallway View



Hallway entrance from dining room



Hallway to Master Bedroom Entrance



Master Bedroom (Ceiling Fan to replace)



Master bedroom to Bathroom Entrance



Master bathroom



Master Bathroom (Toilet)



Master Bathroom 16" Step into Bathtub



Hallway View to Guest Bathroom (left)



and Guest Bedroom (Straight)



Guest Bathroom (from Hallway Entrance)




Guest Bathroom Tiny Shower



Guest Bedroom

Guest Bedroom



North Side of Carport and Home

East Side – Street View of Drive way.



North West Corner Entrance of Home





North West Corner of Home



South West Corner of Home



Street View Orientation



South Side of Home facing Bridge



HVAC System (Outside) on West side of house **Newly installed by our WX team*



HVAC System (Inside Dining Room Closet) * Newly installed by our WX team



Electrical Meters, Panels, Breaker Boxes, etc.




Gas Meter (South side wall of home) / Breaker Box in Hallway ^



Water Heater (Gas Unit) *Newly installed by our WX team



Refrigerater



Whirlpool Corporation, U.S.A., Benton Harbor MI 49022. Whirlpool Canada LP., Mississauga, ON 16N 3A7 licensee/porteur de licence au Canada

FOR PARTS AND SERVICE GIVE MODEL NO., AND SERIAL NO.
 POUR PIÈCES ET SERVICE MENTIONNER NUMERO DE MODELE ET NUMERO DE SERIE

ASSEMBLED IN U.S.A. ASSEMBLÉ AUX ÉTATS-UNIS
 USA 1-800-688-9900
 CANADA 1-800-888-2002
 MEX.CO 01800-054-5454
 WWW.MAYTAG.COM

HOUSEHOLD REFRIGERATOR
 165A TYPE BMA19

4.25 oz R134a
 121 g de R134a
 115VAC/60HZ
 7.10 A
 CODE 21

ALSO LISTED IN ACCORDANCE WITH NSF/ANSI 372 3YR

MOD# MBF1953YEW2
 SER# K31705173

USE ICE MAKER KIT IC13B
 UTILISEZ L'ENSEMBLE D'ACCESSOIRES POUR MACHINE À GLAÇONS IC13B
 MINIMUM INSTALLATION CLEARANCE TOP - 3/4 INCH
 ESPACE DE DÉGAGEMENT REQUIS - 3/4


EEV109900

UL US LISTED
 AHAM VERIFIDE
 Energy Star

Gas Stove with Controls at Front.

**Our organization recently installed this new stove through a local private donation.*





Driveway

101 Fenner St

Cuero, TX

Dorothy Brown

AC

Front Porch

